

Sale Name: September 2024 Government / Contractor Surplus Auction

LOT 303 - 2006 GMC Savana 2 Door Regular Cab Dually Box Truck with Lift Gate (142,261 Miles)



Make GMC

Model Savana

VIN 1GDJG31U961224188

Miles 142,261

Description

Make: GMC

Model: Savana

Year: 2006

VIN: 1GDJG31U961224188

Mileage: 142,261

Transport Dimensions: 305" L x 99" W x 123" H

GVWR: 12,300 lbs

Features

A/C/Heat/Defrost

AM/FM

Cruise

Box Bed- 197" L x 92" W x 83" H

Door Opening: 86" W x 76" H

Lift Gate

Side Entry door to Box

Specifications

Title: Clear

Engine

Make: GM

Type: V-8, 6.0L

Fuel Type: Gasoline

Transmission

Type: Automatic

Tire Size: 245 75 16

Brake Type: Hydraulic

This truck belongs to a local contractor who is updating their fleet. The truck will crank, run, drive the check engine light is on (see codes), the transmission will shift properly, the brakes are good, the tires are showing some wear but still holding air, the exterior has some paint peeling and down to the bare metal in some spots, the driver seat has a tear, the lift gate is not working properly, the roll up door is in bad shape, the floor in the box has some bad spots, the A/C is blowing cool through the defrost vents, the truck drives good.

Engine Codes:

P0030-primary oxygen sensor malfunctioning

P0036-indicates a problem with the heater control circuit for the downstream oxygen sensor (O2S) in bank 1 of a vehicle's engine

P0050-relates to the issues the Engine Control Module (ECM) finds with the heater control circuit of the primary oxygen sensor 1 on the bank 2 side of the engine.

P0053-indicates a problem with the heated oxygen sensor (HO2S) heater resistance in bank 1, sensor 1

P0054-HO2S Heater Resistance (Bank 1, Sensor 2)

P0059-HO2S Heater Resistance (Bank 2, Sensor 1)

P0154-O2 Sensor Circuit No Activity Detected (Bank 2, Sensor 1)

P0449-EVAP system vent valve solenoid is malfunctioning

P0135-engine control module (ECM) has tested the O2 sensor heater circuit and has detected a problem with the O2 sensor heater circuit in bank 1 sensor

P0141-Oxygen Sensor Heater Circuit Malfunction (Bank 1, Sensor 2)

P0155-indicates a problem with the heated oxygen sensor circuit on Bank 2 of a vehicle's engine

Mississippi Residents – If you are from Mississippi and plan to title the unit in our State, we will have to add 5% sales tax to the high bid price and charge a \$10 title fee, no exceptions unless you are dealer. This does not apply to anyone titling a vehicle out of State, all out of State buyers will be invoiced the exact bid price and will register/title and pay any taxes/fees in his/her State!

Each and every Lot is sold "as is, where is". JJ Merchant provides no guarantees or warranties (express or implied) in respect of the item contained in the Lot. All representations made by JJ Merchant, its servants or agents are to be considered lay opinions only and JJ Merchant accepts no liability for any purchase made by a Buyer in reliance upon them.

Quantity: 1



<https://www.jjmerchant.com/>